
APPENDIX D Project Location & Existing Conditions



Project site location. 23363 Mountain Dr., Twain Harte, Ca

GPS Coordinates: 38.045823°N, -120.228031°W



Plan view of site.

TITLE: PROJECT SITE LOCATION

PROJECT: WATER TANK RECOATING AND UPGRADE PROJECT

DATE: 4/23/2018 Appendix D-1



MG#1. Existing roof hatch area.




MG#1. Existing exterior ladder. There is no existing fixed portion of ladder below the platform.

TITLE: MG#1 EXISTING ROOF, PLATFORM AND LADDER PROJECT: WATER TANK RECOATING AND UPGRADE PROJECT

DATE: 4/23/2018 Appendix D-2



MG#1 existing rafter and shell clip and extent of roof structure replacement at the shell.




MG #1 existing interior center support and rafters.

TITLE: MG#1 EXISTING INTERIOR ROOF

PROJECT: WATER TANK RECOATING AND UPGRADE PROJECT

DATE: 4/23/2018 Appendix D-3



MG#1 center column base plate and extent of roof structure replacement at the bottom.



MG#2 Existing roof hatch, guardrail and appurtenances.

TITLE: EXISTING CONDITIONS MG#1 AND MG#2

PROJECT: WATER TANK RECOATING AND UPGRADE PROJECT

DATE: 6/14/2018 Appendix D-4



MG#2 Existing ladder platform



MG#2 existing rafter and shell clip and extent of roof structure replacement at the shell.


TITLE: EXISTING CONDITIONS MG#2

PROJECT: WATER TANK RECOATING AND UPGRADE PROJECT

DATE: 5/21/2018 Appendix D-5



MG #2 existing interior center support and rafters.



MG#2 center column base plate and extent of roof structure replacement at the bottom.

TITLE: EXISTING CONDITIONS MG#2 ROOF STRUCTURE
PROJECT: WATER TANK RECOATING AND UPGRADE PROJECT

DATE: 5/21/2018 Appendix D-6